EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	13	("3932726" "5609284" "6112967" "6211488" "6252197").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 08:21
L2	0	1 and (dioxide co2)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 08:44
L3	830	glass with (dioxide co2) with laser	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 08:45
L4	17	glass with (dioxide co2) with laser near3 cut\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 08:46
L5	2	glass with cut\$4 and laser with (dioxide co2) and plan\$2 near2 dens\$5 and volume near2 dens\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 09:06
L6	3	glass with cut\$4 and laser with (dioxide co2) and laser same plan\$2 with dens \$5 and laser same volume with dens\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 09:07

L7	2	glass with (notch \$4 crack\$4) and (heat\$3 absorb \$4) with (laser irradiat\$4) with (dioxide co2) and laser same (plan\$2 volume) near3 dens\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR		2008/03/02 09:13
L8	4	glass with (notch \$4 crack\$4) and (heat\$3 absorb \$4) with (laser irradiat\$4) with (dioxide co2) and laser same energ\$4 near3 dens\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OS	2008/03/02 09:13
L9	12	glass with (notch \$4 crack\$4 break \$4) with (laser irradiat\$4) and synchro\$11 with (transfer\$4 translat\$4 mov \$5) with (output \$3 \$3radiat\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 09:52
L10	162	(glass ceramic brittle\$4) with (notch\$4 crack\$4 break\$4) with (laser irradiat\$4) and (synchro\$11 control\$4) near4 (transler\$4 translat\$4 mov \$51 and (synchro\$11 control\$4) near4 (output\$3 \$3 radiat\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	O.	2008/03/02 09:56

L11	112	(glass ceramic brittle\$4) with (notch\$4 crack\$4 break\$4) with laser and (synchro\$11 control\$4) near4 (transfer\$4 translat\$4 mov \$5) same (synchro\$11 control\$4) near4 (output\$3 \$3radiat\$5)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ØS .	2008/03/02 09:57
L12	106	11 not 9	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 09:57
L13	15	11 not 9 not (tsikos knowles). in.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:02
L14	75	laser same first adj control\$4 adj (part means device unit) and laser same second adj control\$4 adj (part means device unit)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:20
L15	25106	laser with (weld \$4 cut\$4 melt\$4 etch\$4 trim\$4 textur\$4 drill\$4 punch\$4) same control\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:22
L16	11	14 and 15	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:22
L17	3	16 and densit\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:23

L18	3	16 and suction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:34
L19	0	14 and water near3 suction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:34
L20	1	14 and water with suction	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:34
L21	0	14 and water with suck\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:35
L22	12	15 and water with (suck\$4 suction\$4) with cool\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:35
L23	2	15 and notch\$4 with crack\$4 with ultra adj hard	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:38
L24	2	15 and notch\$4 with crack\$4 with (ultrahard ultra?hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:39
L25	2	15 and (notch\$4 crack\$4) with (ultrahard ultra? hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:39
L26	О	15 and scor\$4 with (ultrahard ultra?hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	OR	ON	2008/03/02 10:40

L27	1	15 and (groov\$4 etch\$\$) with (ultrahard ultra? hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:40
L28	1	15 and (groov\$4 etch\$4) with (ultrahard ultra? hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:40
L29	20	glass and (scrib \$4 groov\$4 etch \$4) with (ultrahard ultra? hard)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 10:41
L30	5	(glass with (scrib \$4 groov\$4 etch \$4) with break\$4 with laser).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 11:17
L31	22	(glass with break \$4 with laser). clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 11:18
L32	78	"65"/\$.ccls. and (glass with laser). ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 11:19
L33	50	32 and (glass with laser).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/03/02 11:20

^{3/2/2008 11:29:35} AM

C:\ Documents and Settings\ SHeinrich\ My Documents\ EAST\ Workspaces\ 10541198. wsp